



SERVICE BULLETIN

SB No. **L-410/074b** Aeroplane Type: **L-410**

Revision No. IR Date of Issue: Oct 30, 2023

The technical content of this document is approved under the authority of the DOA ref. EASA.21J.119.

Classification: Recommended

Subject: Installation of teflon (PTFE) washers under screws of covers.

Supersedure: N/A

1. PLANNING INFORMATION

A. APPLICABILITY

L-410 UVP - Turbolet, L 410 FG, L 410 UVP-LW.

B. CONCURRENT REQUIREMENTS

None.

C. REASON

Teflon washers prevent paint from abrasion during periodic maintenance.

D. COMPLIANCE TIME

As per operator's requirement.

E. MANPOWER

Supposed Man-hours: not specified.

F. MATERIAL

Will be delivered by the aeroplane manufacturer Aircraft Industries, a.s., 686 04 Kunovice, Czech Republic based on order.

G. NEW EQUIPMENT

None.



H. SPECIAL TOOLS

None.

I. EXPENSES

To be covered by the operator.

J. WEIGHT AND BALANCE

Influence of the installation on an empty aeroplane weight and moment is negligible.

K. REFERENCE DOCUMENTS

1. Drawings

B522 228N

PTFE Washers

2. Maintenance Manual L 410 UVP or L 410 UVP-LW, chap.:

20.20.00

L. AFFECTED DOCUMENTS

AFM not affected MS not affected MM not affected WM not affected

2. IMPLEMENTATION INFORMATION

A. PREPARATORY WORK

None.

B. CHECK OR INSPECTION

None.

C. DISASSEMBLY

- Remove appropriate covers during periodic maintenance according to the Dwg No. B522 228N sheet 1 (L-410 UVP – Turbolet, L 410 UVP-LW aeroplanes) or sheet 2 (L 410 FG aeroplanes).
- Repair damaged paint under head screws according to the MM, chap. 20.20.00.

Page: 2 Revision No. IR



D. ASSEMBLY

• Put on a teflon washer between original metal washer (if installed) and an appropriate cover. Use material pos. 1 or 2 of point 3.A. of this bulletin.

E. TESTS

1. Ground Tests

None.

2. Flight Tests

None.

F. COMPLETION WORK

• Install back removed covers.

3. BILL OF MATERIAL

A. MATERIAL DELIVERED BY THE AEROPLANE MANUFACTURER

Pos.	Nomenclature	Name	Pcs/ArpIn
1	B522114N	4 Teflon (PTFE) washer	620
2	B522113N	5 Teflon (PTFE) washer	400

4. RECORD IN THE AEROPLANE LOGBOOK

Record implementation of this L-410/074b Service Bulletin.

Revision No. IR Page: 3



