



Aircraft Industries



www.let.cz / pps@let.cz / +420 572 817 664
Aircraft Industries, a.s. / Na Záhonech 1177 / Kunovice 686 04 / Czech Republic

SERVICE LETTER

SL No. **L-410/008**

Aeroplane Type: **L-410**

Model(s): **L 410 UVP-E, E9, E20**

Date of Issue: **Jun 24, 2021**

Reason: Check of a sleeve on the nose landing gear leg.

Description: Turning of the sleeve may disable the LG from retracting.

1. Check via the red line that the sleeve has not been rotated – see Fig. 1.
2. Check correct tightening of the nut on the sleeve (6 to 7 Nm).

If the sleeve has been rotated, contact AI a.s.



Fig. 1 The sleeve on the nose landing gear leg