



Aircraft Industries



www.let.cz / pps@let.cz / +420 572 817 664
Aircraft Industries, a.s. / Na Záhonech 1177 / Kunovice 686 04 / Czech Republic

SERVICE LETTER

SL No. **L-410/020**

Aeroplane Type: **L-410**

Model(s): **L 410 UVP, UVP-E20**

Date of Issue: **July 08, 2025**

Reason: Occurrence of the autopilot buffeting on the ground.

Description: In specific cases during ground test, the autopilot may exhibit buffeting in the pitch and roll axes. This Service Bulletin is applicable only to aircraft with **GARMIN G700TXi (approved under EASA STC 10084417 rev. 2)** installed with combination of **Honeywell KFC 325 Autopilot**.

Aircraft Industries, a.s. thereby informs L-410 operators that the required measures related to autopilot buffeting on the ground are described in Service Bulletin SB_AE231-01 Rev. A (applicable to L 410 UVP-E20, from SN 3414 and newer ones meeting the note mentioned in the description upper) and Service Bulletin SB_AE231-02 IR (applicable to L 410 UVP, only for SN 820738 and SN 820739).

The bulletins will be sent to the operators by the original STC holder, AEROSERVIS s.r.o. upon prior request.

Contact: AEROSERVIS s.r.o.
Mr. Radek RAIDA
Head of Airworthiness
e-mail: DOA@aeroservis.aero