



SERVICE LETTER

SL No. **L-410/022**

Aeroplane Type: **L-410**

Model(s): **L 410 UVP-E, E9, E20
L-420
L 410 NG**

Date of Issue: **Jan 29, 2026**

Reason: Newly developed set of oil cooler covers, B596 570N Index E – front air cooling inlet cover, B596 571N Index C – rear air cooling inlet cover and B596 572N Index F – oil cooler body insulation.

Description: When using original oil cooler covers set: B596 570N Indexes A to D, B596 571N Indexes A to B and B596 572N Indexes A to E there may be possible difficulties with securing inlet covers or installation of covers on the body of the oil cooler.

This service letter is issued to inform operators of L-410 aeroplane about the availability newly modified set of oil cooler covers.

The sewing patterns of the cooling air inlet covers and oil cooler body covers have been improved for a better fit.

If you are having trouble with securing the oil cooler inlet covers or installing covers on the oil cooler body, you can order them now.



Install or remove the set of oil cooler covers according to AMM for:

L 410 UVP-E, E9, E20: Doc. No. Do-L410-1232.2, chapter: 79.40.01

L-420: Doc. No. Do-L410-1233.2, chapter: 79.40.01

L 410 NG: Doc. No. Do-L410NG-1230.2, chapter: 79-40-01

To order, please contact the Aircraft Industry After Sales Customer Service department on the email address: pps@let.cz



Front air cooling inlet cover –
B596 570N Index E

Oil cooler body insulation –
B596 572N Index F

Rear air cooling inlet cover
– B596 571N Index C