



Aircraft Industries



www.let.cz / pps@let.cz / +420 572 817 664
Aircraft Industries, a.s. / Na Záhonech 1177 / Kunovice 686 04 / Czech Republic

SERVICE LETTER

SL No. **L-410/018**

Aeroplane Type: **L-410**

Model(s): **All equipped with the
LUN 3170-7 terminal
microswitches except
L 410 NG**

Date of Issue: **Apr 10, 2024**

Reason: Issue of a methodology for replacement and adjustment of the LUN 3170-7 terminal microswitch on the landing gear hydraulic jacks.

Description: Possibility of replacement and adjustment of the LUN 3170-7 terminal microswitch by an aircraft manufacturer authorised person.

This service letter is issued to inform L-410 aircraft operators having aeroplanes equipped with the LUN 3170-7 terminal microswitches about possibility of replacement and adjustment of the terminal microswitch by an AI, a.s. aircraft manufacturer authorised person trained at the JIHLAVAN, a.s. original equipment manufacturer (OEM).

The hydraulic jack with terminal microswitch does not have to be sent to the OEM in the Czech Republic and the replacement can be accomplished directly at an operator.