



www.let.cz / pps@let.cz / +420 572 817 664
Aircraft Industries, a.s. / Na Záhonech 1177 / Kunovice 686 04 / Czech Republic



Aircraft Industries

SERVICE LETTER

SL No. **L-410/024**

Aeroplane Type: **L-410**

Model(s): **L 410 NG**

Date of Issue: **Mar 16, 2026**

Reason: **Fixing of the GARMIN G3000 system short-term outages when some GPUs with low voltage disconnection threshold are used.**

Description: Service Bulletin SB 121b for S/N 5006 has been issued to fix the issue.

This service letter is issued to inform L-410 aircraft operators of the availability of a general technical solution to fix short-term outages of the GARMIN G3000 system following the disconnection of certain types of GPUs. This technical solution can be adapted for other L 410 NG aeroplane serial numbers.

If this issue occurs on your aeroplane and you wish to resolve it, please contact the After-sales service department of Aircraft Industries for a specific solution with respect to the L 410 NG aeroplane serial number, at the e-mail address: pps@let.cz