

www.let.cz / pps@let.cz / +420 572 817 664
Aircraft Industries, a.s. / Na Záhonech 1177 / Kunovice 686 04 / Czech Republic

SERVICE LETTER

SL No. **L-410/009** Aeroplane Type: **L-410**

Model(s): All

Date of Issue: **Feb 23, 2022**

Reason: Introduction of the new pressure plates type of the K38-1200-7 brake.

Description: Pressure plates design improvement to increase steadiness.

This service letter is issued to inform L-410 aircraft operators that production of the original pressure plates was cancelled and they are replaced with new ones according to table below:

Designation	Original pressure plate P/N	New pressure plate P/N
Front pressure plate 1	K38-1230.00	K38-3230.00
Double-sided (central) pressure plate 2	K38-1240.00	K38-3240.00
Double-sided-(central) pressure plate 3	K38-1250.00	K38-3250.00

NOTE

Rear pressure plate P/N K38-1260.00 remains unchanged.

Original pressure plates stated in the table above cannot be ordered and delivered, only new plates are available.

Instructions for continuous airworthiness and illustrated parts catalogue will be amended by next revision.