



SERVICE LETTER

SL No. **L-410/010** Aeroplane Type: **L-410**

Model(s): **L 410 UVP-E20**Date of Issue: **Jul 19, 2022**

Reason: Calendar service life expiration of the recording unit FDR-59 B-L.

Description: Possibility of the prolongation calendar service life for 15 months.

This service letter is issued to inform L-410 aircraft operators that 15 months calendar service life prolongation is possible to arrange replacing of the obsolete flight data recorder.

Based on operator order Maintenance Schedule Appendix will be issued for specific serial number of the aeroplane.

Contact aeroplane manufacturer pps@let.cz for Maintenance Schedule Appendix order and payment information.