



SERVICE LETTER

SL No. **L-410/023**

Aeroplane Type: **L-410**

Model(s): **All except L 410 FG**

Date of Issue: **Jan 29, 2026**

Reason: Newly developed set of blind flanges of static pressure probes
B953 322N Index K.

Description: When using original blind flanges sets B953 322N Indexes D to J into static
pressure probes there is a possible risk of losing the blind flange set.

This service letter is issued to inform operators of L-410 aeroplane about the availability of newly modified set of static pressure probe blind flange set.

The original version consisted of two parts where O-ring tended to separate. The newly developed set is made from a single piece of polyamide with a tapered body.

If you have an issue with losing static pressure probe blind flange set, you can order them now.

To order a complete set, please contact the Aircraft Industry After Sales Customer Service department on the email address: pps@let.cz

